

# **EXHIBIT A**

**City of Laverne Police Report  
State of Tennessee**

Accepted Date 6/12/2019 8:11 AM  
 Generated Date 6/12/2019 8:11 AM  
 Report Form Level 3



Master Record Number	102416192
Type Of Crash	Suspected Minor Injury
Approved By	3110

## Tennessee Electronic Traffic Crash Report

### Incident Information

Date of Crash 6/11/2019	Day Of Crash Tuesday	Local Agency Number 0750300	Reporting Agency Name Laverne Police Dept	Agency Tracking Number 19-022531
Time of Crash 12:15	Time Notified 12:16	Time Arrived 12:20	County Rutherford	City Laverne
Total Vehicles 2	Total Occupants 3	Total Non-Occupants 0	Total Killed 0	Total Injured 2
Hit and Run No	Solved No	Police Pursuit No	School Bus Involved No	Photos Taken No
Area Not Applicable	Interchange Related No	Intersection Type OTHER	By Photographer Name	Total Uninjured 1
Block Number	Roadway Number	Roadway Name RAMP	Suffix	Mile Marker 0.00
Estimated Distance	Distance Type	Direction	From Highway/Intersection I 24	Suffix Intersect Number
Roadway Local Id	Intersect Local Id			
Relation To Junction Entrance/Exit Ramp Related	Relation to Roadway On Roadway			Route Signing Unknown
Work Zone None	Construction Zone			
Construction Location	Workers Present			
First Harmful Event Motor Vehicle-In-Transport On Same Roadway	Trafficway Type Trafficway-CLOSED			
Weather Conditions Cloudy	Light conditions Daylight	Latitude 35.994380	Longitude -86.596850	Rail Crossing Id
Manner of Collision Sideswipe, Same Direction	1st Collision Factor			
2nd Collision Factor		3rd Collision Factor		

### Incident Management

Secondary Crash No	Secondary Crash Type	Blockage Occurred Yes
Roadway / Lanes Blocked Jun 11 2019 12:10PM	Roadway Lanes/ Cleared Jun 11 2019 12:55PM	
Lanes Blocked Lane 1		
Incident Started Jun 11 2019 12:15PM	Incident Cleared Jun 11 2019 12:55PM	

### Investigating Officer Details

Investigation Complete Yes	Rank FTO	First Name BILLY	Middle Initial	Last Name DUENEZ	Suffix
Badge Number 286	District/Zone 1	Car Number 13-25	Report Date 06/11/2019		

### Assisting Officers

Rank OFC	First Name HARRY	Middle Name	Last Name HOLLINS	Suffix
Badge Number 324	District / Zone 3	Car Number 324	Report Signed	Report Date

Vehicle Number 1	Number of Occupants 1	Driver Presence Driver Operated
---------------------	--------------------------	------------------------------------

**Driver Information**

First Name <b>JAMES</b>		Middle Initial <b>ROBERT</b>	Last Name <b>MEADOR</b>		Suffix	Date Of Birth	Age <b>59</b>
Address Line 1		Address Line 2		City	State	Zip Code	
Phone 1	Phone 2	Phone 3	Race <b>Caucasian Mexican Puerto Rican Other White</b>	Ethnicity <b>Non-Hispanic</b>		Gender <b>M</b>	
Drivers License Number		Drivers License State		Expiration Date <b>2020</b>	Drivers License Class <b>A</b>	Drivers License Status <b>Valid</b>	
Safety Equipment <b>Shoulder And Lap Belt Used</b>				Airbag <b>AirBag Available-No Deployment</b>		Seat Position <b>Front Seat-Left Side</b>	
Endorsement 1 <b>None</b>		Complied With		Endorsement 2		Complied With	
Restriction 1 <b>Unknown</b>		Complied With		Restriction 2		Complied With	
Ejected <b>Not Ejected</b>		Ejection Path		Trapped/Extricated <b>Not Trapped</b>			
Injury Code <b>No Injury</b>		Medical Transport <b>Not Transported</b>		Ambulance/Hospital			

**Driver Conditions and Actions**

Hit and Run <b>No Hit And Run</b>		Driver/Vehicle Maneuver <b>Other</b>		Distraction <b>None</b>	
Driver's 1st Condition <b>Appeared Normal</b>		Driver's 2nd Condition		Driver's 3rd Condition	
Driver's 1st Action <b>Improper Turn</b>		Driver's 2nd Action			
Driver's 3rd Action		Driver's 4th Action			

**Alcohol and Drugs**

Presence of Alcohol <b>No</b>		Determination Method <b>Observed</b>		Alcohol Test Status <b>Test Not Given</b>	
1st Alcohol Test Type	1st Alcohol Test Result	2nd Alcohol Test Type	2nd Alcohol Test Result		
Presence of Drugs <b>No</b>		Determination Method <b>Observed</b>		Drug Test Status <b>Test Not Given</b>	
1st Drug Test Type	1st Drug Test Result	2nd Drug Test Type	2nd Drug Test Result	3rd Drug Test Type	3rd Drug Test Result

**Driver Violations**

1st Violation	1st Violation Category	1st Violation Description	1st Violation Statute
2nd Violation	2nd Violation Category	2nd Violation Description	2nd Violation Statute
3rd Violation	3rd Violation Category	3rd Violation Description	3rd Violation Statute
4th Violation	4th Violation Category	4th Violation Description	4th Violation Statute
5th Violation	5th Violation Category	5th Violation Description	5th Violation Statute



## Vehicle Information

Owner Same as Driver No		Owner First Name ANTHONY		Owner Middle Name LEROY		Owner Last Name KRAUSE		Owner Suffix	
Address Line 1			Address Line 2			City		State / Zip Code	
Phone 2		Phone 3		Vehicle Year 2018		Vehicle Make DODG		Vehicle Model R35	
VIN		License Plate Number		State Texas		Plate Expiration 102019		Color White	
HAZMAT? No		FMCSA Reportable? Yes		Bus Use Not Used As School Bus		Unit Type Motor Vehicle In-Transport		Body Style Standard Pickup	
Gross Weight 10001 To 26000				Vehicle Configuration Truck Trailer					
Vehicle Operation Type Commercially Owned/Used				Cargo Body Type Flatbed					
1st Factor NONE			2nd Factor			3rd Factor			
Vehicle Special Use No Special Use				Emergency Use No		Override/Underride			
Towed Driven From Scene			Towed Location						
1st Trailer Other Trailer		1st Trailer License Plate Information TX 006F081 000000		2nd Trailer		2nd Trailer License Information			
Insurance 1 A425171442		Insurance 1 Type Unknown		Insurance 1 Carrier HALLMARK COUNTY MUTUAL		Insurance 1 Start Date 3/30/2019		Insurance 1 End Date 3/30/2020	
Insurance 2		Insurance 2 Type		Insurance 2 Carrier		Insurance 2 Start Date		Insurance 2 End Date	
Insurance 3		Insurance 3 Type		Insurance 3 Carrier		Insurance 3 Start Date		Insurance 3 End Date	

## Vehicle Damage and Roadway Characteristics

Most Harmful Event Motor Vehicle-In-Transport On Same Roadway			Fire in Vehicle No		
Events 1 Motor Vehicle-In-Transport On Same Roadway		Events 2		Events 3	
Events 4		Events 5		Events 6	
Point of First Impact Right Side-Center		Extent of Damage Minor Damage		Officer Damage Estimate Less Than Threshold	
Areas of Vehicle Damage Right Side-Center					
Travel Direction North		Traveling On WALDRON ROAD			
Trafficway Flow Entrance Exit Ramp		Roadway Surface Type Asphalt		Number of Travel Lanes One Lane	
Trafficway Hazards None					
Traffic Control Devices Yield Sign		Traffic Control Device Functioning Device Functioning Properly		Roadway Route Signing Unknown	
Roadway Surface Conditions Dry		Roadway Character Alignment Curve Right		Roadway Character Profile Uphill Grade	
Speed Limit 30		Access control Full Control Only Ramp Entry and Exit			

## Commercial Carrier Information

US DOT 02591311		Carrier Name TK TRANSPORT INC		Carrier Type Other Operation-Not Specified		ICC MC		TN DOS TN	
Address Line 1			Address Line 2			City clute		State / Zip Code TX 77521	
1st Hazardous Materials		HAZMAT Class		Placard		Placard #		Released	
2nd Hazardous Materials		HAZMAT Class		Placard		Placard #		Released	
3rd Hazardous Materials		HAZMAT Class		Placard		Placard #		Released	

Vehicle Number 2	Number of Occupants 2	Driver Presence Driver Operated
---------------------	--------------------------	------------------------------------

## Driver Information

First Name ANGELA	Middle Initial LYNNETTE	Last Name HARRIS	Suffix	Date Of Birth	Age 45
Address Line 1		Address Line 2		City	State
Phone 1	Phone 2	Phone 3	Race Black or African American	Ethnicity Non-Hispanic	Gender F
Drivers License Number	Drivers License State	Expiration Date 2019	Drivers License Class C	Drivers License Status Valid	
Safety Equipment Shoulder And Lap Belt Used			Airbag AirBag Available-No Deployment		
Endorsement 1 None	Complied With	Endorsement 2	Complied With	Endorsement 3	Complied With
Restriction 1 Unknown	Complied With	Restriction 2	Complied With	Restriction 3	Complied With
Ejected Not Ejected	Ejection Path		Trapped/Extricated Not Trapped		
Injury Code Suspected Minor Injury	Medical Transport EMS-Ground	Ambulance/Hospital STONECREST MEDICAL CENTER			

## Driver Conditions and Actions

Hit and Run No Hit And Run	Driver/Vehicle Maneuver Stopped In Traffic Lane	Distraction None
Driver's 1st Condition Appeared Normal	Driver's 2nd Condition	Driver's 3rd Condition
Driver's 1st Action None	Drivers 2nd Action	
Driver's 3rd Action	Driver's 4th Action	

## Alcohol and Drugs

Presence of Alcohol No	Determination Method Observed	Alcohol Test Status Test Not Given
1st Alcohol Test Type	1st Alcohol Test Result	2nd Alcohol Test Type
		2nd Alcohol Test Result
Presence of Drugs No	Determination Method Observed	Drug Test Status Test Not Given
1st Drug Test Type	1st Drug Test Result	2nd Drug Test Type
		2nd Drug Test Result
		3rd Drug Test Type
		3rd Drug Test Result

## Driver Violations

1st Violation	1st Violation Category	1st Violation Description	1st Violation Statute
2nd Violation	2nd Violation Category	2nd Violation Description	2nd Violation Statute
3rd Violation	3rd Violation Category	3rd Violation Description	3rd Violation Statute
4th Violation	4th Violation Category	4th Violation Description	4th Violation Statute
5th Violation	5th Violation Category	5th Violation Description	5th Violation Statute



**Vehicle Information**

Owner Same as Driver No		Owner First Name EDWIN		Owner Middle Name ELISHA		Owner Last Name BRANNEN		Owner Suffix JR	
Address Line 1			Address Line 2			City		State	
Phone 2		Phone 3		Vehicle Year 2001		Vehicle Make FORD		Vehicle Model F15	
VIN		License Plate Number		State		Plate Expiration 012020		Color Black	
HAZMAT? No		FMCSA Reportable? No		Bus Use Not Used As School Bus		Unit Type Motor Vehicle In-Transport		Body Style Standard Pickup	
Gross Weight 10000 or Less-No Haz-8 Or Less					Vehicle Configuration				
Vehicle Operation Type Personally Owned/Used					Cargo Body Type				
1st Factor NONE			2nd Factor			3rd Factor			
Vehicle Special Use No Special Use					Emergency Use No		Override/Underide		
Towed Towed Due To Vehicle Damage				Towed Location EASY TOWING 670 OLD NASHVILLE HWY					
1st Trailer		1st Trailer License Plate Information		2nd Trailer			2nd Trailer License Information		
Insurance 1		Insurance 1 Type No Proof Provided		Insurance 1 Carrier			Insurance 1 Start Date		Insurance 1 End Date
Insurance 2		Insurance 2 Type		Insurance 2 Carrier			Insurance 2 Start Date		Insurance 2 End Date
Insurance 3		Insurance 3 Type		Insurance 3 Carrier			Insurance 3 Start Date		Insurance 3 End Date

**Vehicle Damage and Roadway Characteristics**

Most Harmful Event Motor Vehicle-In-Transport On Same Roadway				Fire in Vehicle No	
Events 1 Motor Vehicle-In-Transport On Same Roadway		Events 2		Events 3	
Events 4		Events 5		Events 6	
Point of First Impact Left Side-Near Rear		Extent of Damage Disabling Damage		Officer Damage Estimate Greater Than Threshold	
Areas of Vehicle Damage Left Side-Near Rear, Left Side-Center, Left Side-Far Front					
Travel Direction North		Traveling On 64E EXIT RAMP AT WALDRON ROAD			
Trafficway Flow Entrance Exit Ramp		Roadway Surface Type Asphalt		Number of Travel Lanes One Lane	
Trafficway Hazards None					
Traffic Control Devices Yield Sign		Traffic Control Device Functioning Device Functioning Properly		Roadway Route Signing Unknown	
Roadway Surface Conditions Dry		Roadway Character Alignment Curve Right		Roadway Character Profile Uphill Grade	
Speed Limit 30		Access control Full Control Only Ramp Entry and Exit			

Person Type <b>Passenger</b>							
First Name <b>LESHONA</b>		Middle Name <b>ELAINE</b>		Last Name <b>ROBERTS</b>		Suffix	
Address Line 1 [REDACTED]		Address Line 2 [REDACTED]		City [REDACTED]		State [REDACTED]	
Phone 1 [REDACTED]		Phone 2 [REDACTED]		Phone 3 [REDACTED]		Zip Code [REDACTED]	
Airbag <b>AirBag Available-No Deployment</b>		Safety Equipment <b>Other</b>		Seating Position <b>Front Seat-Right Side</b>			
Ejected <b>Not Ejected</b>		Ejection Path		Trapped/Extricated <b>Not Trapped</b>			
Injury Code <b>Suspected Minor Injury</b>		Medical Transport <b>EMS-Ground</b>		Ambulance/Hospital <b>STONECREST MEDICAL CENTER</b>			

**Alcohol and Drugs**

Presence of Alcohol <b>No</b>		Determination Method <b>Observed</b>		Alcohol Test Status <b>Test Not Given</b>	
1st Alcohol Test Type		1st Alcohol Test Result		2nd Alcohol Test Type	
2nd Alcohol Test Result		2nd Alcohol Test Type		2nd Alcohol Test Result	
Presence Of Drugs <b>No</b>		Determination Method <b>Observed</b>		Drug Test Status <b>Test Not Given</b>	
1st Drug Test Type		1st Drug Test Result		2nd Drug Test Type	
2nd Drug Test Result		2nd Drug Test Type		2nd Drug Test Result	
3rd Drug Test Type		3rd Drug Test Result		3rd Drug Test Result	

**Violations**

1st Violation	1st Violation Category	1st Violation Description	1st Violation Statute
2nd Violation	2nd Violation Category	2nd Violation Description	2nd Violation Statute
3rd Violation	3rd Violation Category	3rd Violation Description	3rd Violation Statute
4th Violation	4th Violation Category	4th Violation Description	4th Violation Statute
5th Violation	5th Violation Category	5th Violation Description	5th Violation Statute

**Commercial Carrier Information**

US DOT		Carrier Name		Carrier Type		ICC MC		TN DOS	
Address Line 1		Address Line 2		City		State		Zip Code	
Phone		Phone		Phone		Phone		Phone	
1st Hazardous Materials	HAZMAT Class	Placard	Placard #	Released	Hazardous Materials Released				
2nd Hazardous Materials	HAZMAT Class	Placard	Placard #	Released	Hazardous Materials Released				
3rd Hazardous Materials	HAZMAT Class	Placard	Placard #	Released	Hazardous Materials Released				

Unit 1 driver said he was passing Unit 2 that was stopped in the lane of traffic at the I-24E exit 64 off ramp at Waldron Road. While doing so, the 40 foot trailer he was hauling side swiped the entire driver side of Unit 2. The trailer was hauling large black pipes weighing an approximate 13,000 pounds according to the driver of Unit 1 when asked. Unit 1 trailer had some scuff marks on it and some damage to some of the straps on the trailer.

Unit 2 driver corroborated Unit 1's recollection of events but added her hazards were on when Unit 1 passed her. She said she was stopped in the lane of traffic as her vehicle was having mechanical issues. Unit 1 was driving at a high rate of speed when passing Unit 2. Unit 2 driver said her truck moved when Unit 1 crashed into her. She complained of neck and hip pain. The passenger said she was in the process of getting in Unit 2 when Unit 1 crashed into them. She complained of neck and back pain. Both subjects were transported to Stonecrest Medical Center in Smyrna by EMS Paramedic 16 for their injuries. No visible injuries were noticed while on scene.

Unit 2 was towed to 670 Old Nashville Highway in La Vergne by Easy Towing. Unit 2 driver said she and her husband were the owners, but had yet to re-register the vehicle.